Incident Report

Incident Classification

Classifying the incident is described in SIP-ADM-13.01.

○Hazard Near Miss

• Minor (Less Than \$25K)

Significant (\$25K - \$500K)

Major (More Than \$500K)

General Information

*Incident Name

10/27/2023 One Call/Encroachment Rapid City Lateral 6" MP

*Incident Start Date

2023-10-27

*Incident Start Time

09:24:00

Incident End Date

2023-10-27

Incident End Time

16:28:00

Incident Report Date

2023-10-27

Incident Report Time

16:24:00

Prepared By:

Wasserburger, William

*Operating Company

Magellan Pipeline Company

*Incident Responsible

Supervisor

Anderson, Ryan

*Location of Incident (where incident occurred)		*Employee/Asset Location (employee home location)	
Other: Rapid City Lateral 6" MP		MPC - Rapid City SD	
Mile Post 110.9 *Incident Address MP 110.9 *Incident City Edgemont *Incident State South Dakota;		*Did incident involve a joint venture (JV)? No *PSM/RMP Asset	
		* OQ Task Involved ○Yes ®No	
		Incident County Fall River	Incident County
*Incident Zip Co 57735	de		
* Area Other			
* District Other			
Incident Descri	ption		
*Who was involv ☐ Magellan Asset Integrity (Field) Employee(s) ☑ Non- Magellan Individual	red in the inciden ☐ Magellan Operations Control Employee(s)	t? ☑ Magellan Operations Employee(s)	□ Magellan Tower Employee(s)
Individual Type Other Individua	Landowner I Type:		
Name: Eric	Nelson	Teleph	one: (605) 890-3162
E	PO Box 409 Edgemont SD 57735	Email:	
Company:	Landowner	□ Acce Termin	ss Suspended or ated

*Incident Description:

On 10/27/2023 at approximately 9:24AM MDT, Hawkeye Helicopter pilot Kolton Kahoon sent a picture of what appeared to be excavation activity around MP 110. After reviewing the photo and determining the landowner, a Magellan technician contacted Eric Nelson at approximately 10:06 AM MDT and asked if he was aware of any excavation on his property, to which he replied, "yes". The Magellan technician told Mr. Nelson that he was not permitted to conduct any further excavation until he had an active one call ticket, and he agreed. A Magellan technician was dispatched to the site and confirmed at 4:17 PM MDT that an excavation approximately 80' from Magellan Pipeline had occurred but no potential for harm to the pipeline had occurred.

*Immediate actions taken:

-Magellan technician contacted the landowner, Eric Nelson to cease any excavation until a one call was submitted and clear, and notified Mr. Nelson he would be turned in to the state one-call board as a violator. -Area supervisor was informed of a one call violation. -Magellan technician dispatched to the scene to gather photos.

Current Status of Incident

Needs Follow-up

Why does the incident require follow-up (be specific)?

One call violation process.

Estimated Cost

\$1

Incident Details

Incident Type			
□ AbnormalOperations(AO)	□ Injury/Illness/ Exposure	□ Motor Vehicle	☑ One Call/Encroach ment
□ ProductQuality□ Other	□ Property Damage	□ Release	□ Security
*Activity at Tir	ne of Incident		
□ Cell Phone In Use		□ Construction	
☐ Driving		 Emergency Response 	
☑ Excavation		☐ Lifting	
☐ Loading/Unloading		☐ Maintenance	
□ Material Handling		Normal Operations	
☐ Office Work		□ Remediation	
□ Repair		□ Shutdown	
□ Start-Up		□ Other	
*Conditions			
☑ Cold		□ Employee <1 Year	
□ Heat		✓ Ice/Snow	

□ Late in Shift	☐ Night/Low Light
□ Normal	□ Overtime
□ Rain	□ Shift Change
□ Tight Space	□ Other
N 4	

0 Notes

One Call/Encroachment Violation Information

Location of Incident

Address MP 110.9

City Edgemont

State South Dakota

Zip 57735

Nearest Intersection Indian

Canyon Rd & County Rd 65

Latitude 43.2479

Longitude -103.7260

Affected Facility Information

Was Pipe or Coating Damaged?

• No.

○Yes

Was the facility part of a joint trench? (A joint trench contains different utilities together in one trench.)

No

Did this event involve a Cross

Bore? (A cross bore occurs when one underground facility is bored through another underground facility.)

○Yes • No

Distance between pipeline and excavation at closest point

80 ft. 0 in.

Measured Depth of Excavation

5 ft. 0 in.

Measured Pipeline depth of cover from existing/undisturbed ground

3 ft. 0 in.

Incident Information

Right-of-Way where event occurred

Pipeline

Type of Excavator

Farmer

Type of Excavation Equipment

Backhoe/Trackhoe

Type of Work Performed

Water

Notification and Locating Information

Was the One-Call Center notified?

○Yes

⊕No

Was work area white-lined?

No

Root Cause

Notification Issue

Subcause

No notification made to One Call Center/

811

Retention: 5 Years