

Incident Report

Incident Classification

Classifying the incident is described in SIP-ADM-13.01.

- Hazard Near Miss Minor (Less Than \$25K) Significant (\$25K - \$500K) Major (More Than \$500K)

General Information

***Incident Name**

11/15/2023 One
Call/Encroachment PLS-Rapid
City Lateral 6 In (7170) Milepost
146.86

Prepared By:

Johring, Mark

***Incident Start Date**

2023-11-15

***Operating Company**

Magellan Midstream Partners

***Incident Start Time**

12:39:00

***Incident Responsible
Supervisor**

Anderson, Ryan

Incident End Date

2023-11-15

Incident End Time

00:40:00

Incident Report Date

2023-11-16

Incident Report Time

09:25:00

***Location of Incident (where incident occurred)**
PLS-Rapid City Lateral 6 In (7170)

Mile Post
146.86

***Incident Address**

***Incident City**

***Incident State**

Incident County
Custer

***Incident Zip Code**

***Area**
Admin

***District**
Admin

***Employee/Asset Location (employee home location)**
MPC - Rapid City SD

***Did incident involve a joint venture (JV)?**
No

***PSM/RMP Asset**
 Yes No

***MP (Mitigation Plan) Asset**
 Yes No

***OQ Task Involved**
 Yes No

Incident Description

***Who was involved in the incident?**

- | | | | |
|--|---|--|---|
| <input type="checkbox"/> Magellan
Asset Integrity
(Field)
Employee(s) | <input type="checkbox"/> Magellan
Operations
Control
Employee(s) | <input type="checkbox"/> Magellan
Operations
Employee(s) | <input type="checkbox"/> Magellan
Tower
Employee(s) |
|--|---|--|---|
- Non-Magellan Individual

Individual Type Landowner

Other Individual Type:

Name: Bob Baker
Address: 27050 Beaver
Valley Road, Buffalo
Gap SD 57722

Company: Rancher

Telephone: (605) 381-1589

Email:

Access Suspended or Terminated

***Incident Description:**

Patrol pilot flying the Rapid City Lateral reported a trencher had been excavating, starting near the pipeline ROW at MP 146.9 near Buffalo Gap, and digging away from the ROW.

***Immediate actions taken:**

Upon receipt of the notification, Rapid City technician Sr responded by dispatching to the site of the observation. Technician visited the site, used electronic locator to locate the line and flagged accordingly. Technician Sr then proceeded to photograph the site and measured from the pipeline to the beginning of the excavation. Technician found that the trencher had begun digging 32 feet east of the pipeline and proceeded to the east, away from the ROW. Technician Sr then proceeded to make contact with the landowner via cell phone as technician Sr is acquainted with the landowner and has contact information. Landowner stated that he had met with Magellan employee several years ago and that pipeline had been crossed at that time and a duct/sleeve was installed to facilitate crossing without digging further into Magellan's easement. This technician Sr has no recollection of the crossing and it is not memorialized on Magellan's P&IDs. The PVC markers for the ends of the sleeves are still in place. As a side note, the site of the historical crossing is also the site of a recent ILI repair excavation.

Current Status of Incident

Resolved

Describe on how the incident was resolved (be specific):

Magellan technician Sr advised that while as a Magellan employee we are not One Call police that technician Sr would have to do the paperwork and submit a report accordingly. Technician Sr encouraged the landowner to put in a One Call request before excavating further. Landowner's trencher is currently on the site, broken down, awaiting repairs.

Estimated Cost

\$0

Incident Details

Incident Type

- Abnormal Operations (AO)
- Injury/Illness/Exposure
- Motor Vehicle
- One Call/Encroachment
- Product Quality
- Property Damage
- Release
- Security
- Other

***Activity at Time of Incident**

- Cell Phone In Use
- Driving
- Excavation
- Loading/Unloading
- Material Handling
- Office Work
- Repair
- Start-Up
- Construction
- Emergency Response
- Lifting
- Maintenance
- Normal Operations
- Remediation
- Shutdown
- Other

***Conditions**

- Cold
- Heat
- Late in Shift
- Normal
- Rain
- Tight Space
- Employee <1 Year
- Ice/Snow
- Night/Low Light
- Overtime
- Shift Change
- Other

0 Notes

One Call/Encroachment Violation Information

Location of Incident

Address 0 out in a pasture
City Buffalo Gap
State South Dakota
Zip 57722
Nearest Intersection Riverside Rd and Beaver Valley Rd
Latitude 43.5066
Longitude -103.2797

Affected Facility Information

Was Pipe or Coating Damaged?

Yes No

Was the facility part of a joint trench? *(A joint trench contains different utilities together in one trench.)*

No

Did this event involve a Cross Bore? *(A cross bore occurs when one underground facility is bored through another underground facility.)*

Yes No

Distance between pipeline and excavation at closest point

32 ft. 0 in.

Measured Depth of Excavation

2 ft. 8 in.

Measured Pipeline depth of cover from existing/undisturbed ground

3 ft. 0 in.

Incident Information

Right-of-Way where event occurred

Pipeline

Type of Excavator

Farmer

Type of Excavation Equipment

Trencher

Type of Work Performed

Agriculture

Notification and Locating Information

Was the One-Call Center notified?

Yes

No

Was work area white-lined?

No

Root Cause

Notification Issue

Subcause

No notification made to One Call Center/
811

Retention: 5 Years