

DAMAGE BILLING TRACKING 2023 INFORMATION										
NO.	Date of Damage	Valid Locate Ticket	Contractor Responsible	At Fault	Address of Damage	City	Billable	File W/ PUC	Action	Description
9	15-Mar-2023	Yes	Underground Construction	Contractor	0 Adams St. alley near 803 Joy St.	Rapid City	Yes	No	Thrown Out	Underground Construction damaged an exposed 2"(p) main while back filling, cutting the line in two causing a release of gas. The locates appear to be accurate. 911 and 811 were notified. I spoke to Corey Osborn with Underground Construction LLC, they are liable for the damage.
23	16-May-2023	Yes	Underground Construction	Contractor	1216 Quincy St	Rapid City	Yes	NO	Warning Letter by DP	Underground Construction cut a 3/4" plastic service with an excavator, EFV activated - 911 not notified. 811 was notified. Locate marks appear to be accurate. Underground Construction is liable for the repair.
37	13-Jun-2023	Yes	Underground Construction	Contractor	1214 COLUMBUS ST	Rapid City	Yes	No	Warning Letter by DP	Underground Construction damaged 2"(p) main and 3/4"(p) service at tap tee. No gas escaping just pipe damage. 811 was notified. Locate marks were accurate.
40	13-Jun-2023	Yes	Underground Construction	Contractor	1214 Columbus St	Rapid City	Yes	No	Warning Letter by DP	Underground Construction damage a 3/4" plastic service and 2" plastic main at the tap tee. No gas escaping but the 2" main needed repair and had to replace the tap tee and EFV. 811 was notified and the locate marks were accurate. Underground Construction is liable for the repairs to the main and service line.
45	26-Jun-2023	Yes	Underground Construction	Contractor	811 12TH ST	Rapid City	Yes	No	Warning Letter by DP	Underground Construction cut a 3/4" plastic service in half with a front-end loader causing a release of gas, EFV tripped, recommended calling 911 and 811 was notified. Locate marks appear accurate but very few marks were visible near the point of dig in due to weather and construction. Underground Construction is liable for the damage.
48	7-Jul-2023	Yes	Underground Construction	Contractor	821 Columbus St	Rapid City	Yes	No	Warning Letter	Underground Construction damaged a 3/4" plastic service with an excavator causing a release of gas, EFV was activated, 811 was notified and 911 was not notified. This is the fifth damage by Underground Construction this year, I have not spoken to Corey Osborn about the potential of MDU filing a complaint, but he is aware of the damage and his responsibility. If MDU precedes on filing the complaint I would like to speak with Corey first. My recommendation is that Underground Construction is liable for the damage and that MDU have on site with safety meeting with Underground Construction before filing a complaint.
51	21-Jul-2023	Yes	Underground Construction	Contractor	805 12TH ST	Rapid City	Yes	No	Warning Letter	Underground Construction severed a 3/4" plastic service with equipment in the alley causing a release of gas, EFV activated, 811 and MDU were notified. Underground Construction is liable for the damage.
68	23-Aug-2023	Yes	Underground Construction	Contractor	811 12th St	Rapid City	Yes	No	Warning Letter	Underground Construction was using equipment within the 18" safe dig zone damaging a 3/4" plastic service causing a release of gas, EFV activated, 811 was notified and 911 was not. Underground Construction is liable.
69	23-Aug-2023	Yes	Underground Construction	Contractor	813 12th St	Rapid City	Yes	No	Warning Letter	During the investigation of the hit line at 811 12th St. MDU discovered that Underground Construction had damaged the tap tee and the black cap was missing. The damaged tap tee was exposed for at least 10 days. 811 was notified. Underground Construction is liable.
70	23-Aug-2023	Yes	Underground Construction	Contractor	Near 1209 Columbus St	Rapid City	Yes	Yes	Pending	MDU was informed of coating damage to a 2" steel main while making repairs to the hit line at 811 12th St. The 2" steel main was exposed, no gas escaping and 811 was not notified. Underground Construction is responsible for the damage.